

QUESTAR SERVICE AND REPAIRFor Telescopes and Accessories

In addition to our Standard Service, Questar is now introducing the "Inspection Service." The <u>Inspection Service</u> takes 1-2 weeks and <u>Standard Service</u> takes 2-4 weeks after approval is given, assuming there is no backlog of instruments to be serviced.

INSPECTION SERVICE:

Basic inspection of mechanical and optical components

Dust off and moderate cleaning of exposed optical surfaces
such as RI surface, barlow, finder lens, and mirror

Check prism – minor adjustment and surface clean Check optical centering and resolution – no adjustment

Check drives (RA and Dec) and motor-minor adjustment only

Check and adjust finder collimation

Wipe down instrument – no buffing or waxing

Supply a report to customer on overall condition of instrument If additional repairs are required an estimate will be furnished

Standard and Duplex Questars \$225.00 plus shipping
Field Model Questar \$145.00 plus shipping
Birder \$200.00 plus shipping

STANDARD SERVICE:

Basic inspection of mechanical and optical components

Disassemble control box, clean, and re-grease moving parts

Clean control box optics Remove and clean prism

Remove and clean main system optics

Check and adjust optical centering

Check and adjust image shift

Check and repair baffle system

Disassemble base assemble and re-grease moving parts

Check and adjust motor and R. A. circle

Adjust finder collimation

Clean Eyepieces (2x) – surface clean and cap

Check solar filters

Wipe down, buff polished parts, and wax scope

Rewrap power cord and tidy up case

Final Inspection

**Diagnostic and Minimum Service Fee \$100.00 plus shipping Ser-110 \$295.00 plus shipping Field Model Questar Ser-114 Standard & Duplex Questars \$425.00 plus shipping Ser-112 \$370.00 plus shipping Birder \$800.00 plus shipping Ser-200 Fully Mounted Questar Seven Ser-202 7" Barrel & Control Box \$450.00 plus shipping Ser-900 700mm \$395.00 plus shipping \$375.00 plus shipping Ser-902 700mm MKII

For international returns, please follow the procedure described in the Return Merchandise Authorization Procedure

Ship to: **Questar Corporation** Phone: 215-862-5277 or 800-247-9607

6204 Ingham Road Fax: 215-862-0512

New Hope, PA 18938 Email: questar@QuestarCorporation.com
USA Web: www.QuestarCorporation.com

Subject to change without notice – effective November 2008 All printed materials are copyright 2008 by Questar Corporation